

RECLINE Calibrator (CAL)

RECLINE: REmote inCLINometer system

Datasheet Version 1.2

January 2017



Calibrator (CAL):

Display:	1 x 16 LCD backlit display
Accuracy:	0.1%
Controls:	1 x Power Switch 2 x Calibration Switches
Indicators:	Low Battery No Sensor Connected No Calibration Cable Connected
Connectors:	Sensor Input: 1 x XLR3, XLR5 or RJ45 etherCON Calibration: 1 x RJ45 etherCON
Power Requirements:	6 x 1.5v AA Batteries (not included)
Operating Temperature:	0°to 40°c
Finish:	Powder Coated – Textured Matt Black
Dimensions:	120mm x 94mm x 53mm (L x W x D)
Weight:	530 grams (including batteries)